



Service Info



LuK DMF 415 0560 10

Modified sensor ring

Manufacturer: Ford

Model: Transit

Model year: 2006 -

Engine: 3,2 TDCi

LuK DMF: 415 0560 10



Figure 1: Variant up to 03/2012



Figure 2: Variant starting from 04/2012

As part of the on-going development of our products, the sensor ring and the bearing arrangement of the dual mass flywheel (DMF) 415 0560 10 has been modified.

The new generation sensor ring differs from its predecessor in that it features a reduced material thickness and a different tooth shape. The use of a ball bearing in place of a friction bearing also extends the service life of the DMF.

Figure 1 shows the DMF configuration used in vehicles up to the production date 03/2012. Figure 2 depicts a DMF as installed in vehicles since 04/2012 and also supplied as a spare part since that date.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

