






| | MEYLE No. | Usable for IVECO Control arm (Ref. No.) |
|------------|-----------------|---|
| Ball joint | 216 010 0006/HD | right upper 500379802 left upper 500379801 |
| | 216 010 0007/HD | right lower 500334716 left lower 500334717 |

Ball joint to fit IVECO Daily II



Lufthansa Technik
Intercoat



|  as OE Problem |  Solution  |
|--|--|
| <ul style="list-style-type: none"> Commercial vehicles are generally subject to severe strains due to overloading and fast driving Authorized dealers only replace complete control arms, resulting in high repair costs | <ul style="list-style-type: none"> Individually replaceable, proven MEYLE HD quality ball joints Extremely long-wearing plastic ball joint sockets designed in cooperation with Lufthansa Technik Intercoat GmbH MEYLE high-tech grease Supplied complete with installation materials |
| Effect | Advantage |
| Rapid wear, resulting in noise from the front axle | <ul style="list-style-type: none"> Quality, long-life ball joints Reduced repair costs for vehicle owners |

