



MEYLE No.
Ball joint: 016 010 0005/HD

Reference No.

0014224V002000000 0015642V002000000

Repair kit,

one-sided: 016 010 0018/HD

0015642V002000000

Repair kit,

both-sided: 016 010 0019/HD

0015642V002000000

Ball joint to fit

Smart









Premature wear due to extremely thin plastic socket and inadequate sheathing of the ball pin

Effect

- Noise from the front end
- Unstable handling
- Inadequate front suspension control





Use of a thicker plastic socket covering a much greater area of the ball

Advantage

A significantly more robust ball joint design results in longer life and less wear



