





MEYLE No. Reference No. 016 010 0002/HD 211 330 04 35

Ball joint to fit Mercedes C219, W/S211, W220









Problem

Heavy loads on ball joints due to deteriorating roads and other factors





- Use of extremely long-wearing plastic ball joint sockets (in aviation tried and tested material)
- MEYLE high-tech grease
- Optimization of material pairing and combination of the components

Effect

- Worn ball joints
- Noise from the axles
- Impaired driving safety

Advantage

Quality, long-life ball joints