





MEYLE No.

Reference No.

Bushing Control arm, left 014 033 0115/HD 203 333 10 14 016 050 0031/HD

203 330 39 11

Control arm, right 016 050 0032/HD 203 330 40 11

Bushing, control arm Mercedes W203, S203, C203, R171, C209, A209









Leakage of hydro fluid due to high dynamic strain and small bonding surface

Effect

- Steering vibration
- Impaired driving safety





Hydro mount replaced by an optimised full-rubbermount with a larger bonding surface

Advantage

- Leakage no longer possible
- Significantly longer service life restriction of driving without comfort

as OE





