



MEYLE
Products®



MEYLE No.

Reference No.

Bushing

814 454 0001/HD

45 45 711

Control arm, right

816 050 9006/HD

45 43 468

Control arm, left

816 050 9005/HD

45 43 450

Control arm bushing to fit Saab 900 II, Cabrio, 9-3



as OE



Problem

High dynamic strain causes leakage of the hydro-liquid

Effect

- Vibration in the steering
- Reduced driving comfort



Solution

Replacing the hydro mount with a full rubber mount

Advantage

No leakage possible and significant longer lifetime without restriction of driving comfort



as OE



Hydro mount

MEYLE-HD-version



Full rubber mount

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • L13.2007

Merkurring 111 • 22143 Hamburg • Germany

contact@meyle.com • www.meyle.com