



**MEYLE**<sup>®</sup>  
Products



	MEYLE No.	Reference No.
Control arm, left	016 050 0056/HD	901 330 24 07
Control arm, right	016 050 0054/HD	901 330 25 07
Ball joint, left + right	036 010 0113/HD	901 333 12 27
Control arm bushing	034 033 0004	901 333 02 14

## Control arm to fit Mercedes Sprinter, VW LT II

as OE

### Problem

Intense strain of the control arm due to overloading of the vehicle and fast driving

### Effect

- Worn out ball joints
- Damaged rubber mounts
- Noise from the front axle




### Solution



- Exchangeable ball joints with improved quality
- Use of extremely long-wearing plastic ball joint sockets (in aviation tried and tested material)
- MEYLE high-tech grease
- Delivery incl. nut
- Exchangeable rubber mounts

### Advantage

Control arm with long service life



Exploded drawing ball joint