



## Service Info



# Visual differences

## affecting tensioner pulley 531 0505 10

Manufacturers: Fiat, Iveco

**Models:**

Fiat: Ducato  
Iveco: Daily

Engines: 2.3 D, 2.3 TD

Part no.: 531 0505 10

**OE number:**

Fiat: 504010846  
504183759



Figure 1: 531 0505 10 — Old version (left) and new version (right)

As part of our continuous efforts to improve our products, changes have been made to the tensioner pulley, part no. 531 0505 10.

This Service Information sheet shows the visual features of the previous version (Figure 1, left) and the new version (Figure 1, right).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

**Observe the specifications of the vehicle manufacturer!**

Spare parts and technical information can be found under [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) or [www.RepXpert.com](http://www.RepXpert.com).

Phone: +44 (0) 14 32 264 264\*  
Fax: +44 (0) 14 32 375 760  
hfd-info@schaeffler.com  
www.schaeffler-aftermarket.com

\* Calls from within the UK 08457 001100

**SCHAEFFLER**  
AUTOMOTIVE AFTERMARKET

