





016 010 0004/HD 016 010 0006/HD 163 330 01 35 163 350 01 13

Ball joints to fit Mercedes W163









Ball joints fail prematurely due to heavy load

Effect

Limited handling of the car coupled with noise from the axial joints





- Black passivation (special process to reduce corrosion)
- Microencapsulation makes nuts self-locking (pink)
- MEYLE high-tech grease developed through marine and wind energy research
- Use of extremely long-wearing plastic ball joint sockets (in aviation tried and tested material

MEYLE-HD version



Advantage

- Significant longer lifetime
- Permanent anti-corrosion coating