





Bushing, control arm, outside Bushing, control arm, inside Left control arm Right control arm Repair kit

MEYLE No. Reference No. 100 407 0013/HD 4A0 407 181 A 100 407 0017/HD 116 050 8200/HD 116 050 8201/HD 100 610 0000/HD

4A0 407 183 D 4A0 407 151 4A0 407 152

Bushing, control arm, front axle (lower) Audi 100, A6









Damage to bushings due to high dynamic strain

Effect

Noise and reduced driving and braking safety





Reinforced bushing design by optimising rubber mixtures and increasing the rubber volume

Advantage

- Significantly longer service life
- Enhanced safety and driving comfort





MEYLE - Miles in Motion