






	MEYLE No.	Reference No.
Bushing	514 610 0006/HD	9443 882 9465 971
Control arm, left	516 050 0017/HD 516 050 0025/HD	3063 5229 30635231
Control arm, right	516 050 0018/HD 516 050 0024/HD	3063 5230 30635232

Bushing, control arm to fit Volvo S60, S80, V70 II, XC 70 Cross Country



 as OE Problem	 Solution 
Leakage of hydro fluid due to high dynamic strain and small bonding surface	Replacing the hydro mount by an optimized full rubber mount leads to an enlarged bonding surface and reduced tension distribution within the rubber
Effect	Advantage
<ul style="list-style-type: none"> • Steering vibration • Impaired driving safety 	<ul style="list-style-type: none"> • Leakage no longer possible • Significantly longer service life without restriction of driving comfort

